



TECHNICAL INFORMATION LETTER

TECHNICAL INFORMATION LETTER No. TIL18MAR2024.REV.IR
DATE : 18/MAR/2024
TO: Affected Weldon Customers
ATTN : TECHNICAL STAFF
SUBJECT : Potential Quality Escape of the following Part Numbers; 18000-B8, 18021-B, 18027-B8, 18030-B, 18031-B, T18009-B8, XC18000-B

Dear Customers,

A Damaged installation tool was discovered/identified for a critical subassembly potentially affecting all part numbers, lot numbers, and serial numbers declared on the page 2 table. While there have been no reported field issues as of this writing, out of an abundance of caution, Weldon is recalling the items identified therein. If you have any questions or concerns regarding the above information, contact the undersigned.

Weldon Pump
640 Golden Oak Parkway
Oakwood, Oh 44146

Phone : 440 232-2282
Fax : 440 232-0606


Sincerely,



18/MAR/2024

Daniel Ramser, Director of Engineer

Approved :



18/MAR/2024

John McClure, Vice President/General Manager

TECHNICAL INFORMATION LETTER No. TIL18MAR2024		
DATE : 18/MAR2024		
PART NUMBER	LOT NUMBER(S)	SERIAL NUMBER(S) [RMA NUMBER(S)]
18000-B8	81538	250605-250611
18021-B	81518	250625
18027-B8	81679	250804
18030-B	81594, 81646, 81686, 81589, 81588, 81747	220345 [4608-1], 228704 [4610-1], 215945 [4618-1], 210873 [4605-1], 202663 [4605-1], 211551 [4629-1]
18031-B	81592, 81591, 81647, 81674, 81677, 81672, 81675, 81676, 81673, 81751	221720 [4599-1], 214904 [4599-1], 209994 [4609-1], 220593 [4613-1], 221714 [4616-1], 213853 [4611-1], 222272 [4614-1], 220587 [4615-1], 211957 [4612-1], 211961 [4556-1]
T18009-B8	81399, 81587, 81648	192206 [4579-1], 250539-250540, 250646-250655
XC18000-B	81714, 81756	250862, 250981